

EVAL INSPECTION — QUICK — EXCAVATORS

2013 John Deere 210G LC Stock: 0U520981 Serial: 1FF210GXJDD520981 Cab w/ AC • Long Arm • Medium Pads • 71 cm Pads • Aux Hydraulics • Less Bucket Warranty Unknown STORAGE LOCATION Brandt Tractor Ltd. / 766542 Bedford, NS, B4B 1H3 Contact:

PHOTOS (18 Total)



SUMMARY

Overall Condition: FAIR

Overall Comments: Machine has been road side mulcher its hole life. -Machine is clean but, scratches and dents at the bottom of the stick aswell as bent step on the upper section of the machine. bucket cylinder has some rust spots on barrel and huge dent on drivers side near counter weight, counter weight itself is scratched like crazy and gouged hard. handles up top are covered in a bunch of surface rust and have terrible weld repairs in places. -machine monitor works as well as all other functions like menu, a/c, heat rabbit or slow, radio, rev switch, etc. the only thing that doesn't work is the windshield wiper and the mulcher monitor wont boot up. -cooling system seems to work and keep the engine at operating temperature and heat and a/c work aswell. - Engine is burning oil and there is a ton of blow bye causing the machine to smoke bad from the engine. oil dipstick is missing (it was checked using another doner dip stick and has oil. there's also quite a bad oil leak from the whole bottom o

Evaluator's Name:Jeramie Downey813Operated Machine:YesHours:14,010

								Estimated Cost		
	E X C	G O O D	A V G	F A I R	P O O R	N / A	Comments	Parts	Labour	Tota
General Appearance			X				clean, bent step, scratches, rust on bars, dents in pannels			
Instruments / Controls		X					works good, everything but windshield wiper & Mulch monitor			
Cooling System Checks		X					cooling system seems to work, keeps engine in range			
Engine Checks			X				burning oil,lots blow bye, missing dip stick, bad oil leak			
Transmission Checks						X				
Differential, Brakes and Final Drive Checks		x					final drives are good, oil a little low but not burnt			
Hydraulic System Checks			X				main hydraulics work, cant start power pack,not sure if work			
Chassis and Frame Checks		X					counter weigth very gouged but other than that good			
Ground Engaging Tools			X				mulcher frame good, bearings good, teeth ok			
Undercarriage			X				track pads and chains really bad, other stuff about 50% left			
Undercarriage Measurements		-	-	-	-	-				

ATTACHMENTS

Γ	Item	Make	Туре	Size	Serial Number	Condition
Г	Other	Denis Cimaf	Power Pack	EWF170	Engine Serial: 73552862	Repair
	Head	Denis Cimaf	Mulcher	DA150	1311HF305	Repair

GROUND ENGAGING TOOLS

% remaining	NEW	G O D	U S A B L E	REP A I R	1	N / A	Comments	Parts	Labour	Total
						X				
						X				
						Х				
						X				
	% remaining	% remaining W	% remaining $\begin{bmatrix} N \\ W \\ D \\ \hline \\ \hline$	% remaining New Google AB % remaining New D E	% remaining N G U R % remaining N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N N <td< td=""><td>% remaining N G V R P A A A A A A A A C A A C A A C A A C A A C A A C A A C A A C A A C A C A C A C A C A C A C A C C A C C A C C A C C C A C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C</td><td>% remaining N W W G O D A B E A A A E N A A A A A % remaining N W D I I I X I I I I I X I I I I I X I I I I I X I I I I I X I I I I I X</td><td>% remaining N W G O D A E A A A A N A Comments % remaining N W I I I I A Comments I I I I I I X has a mulcher not a bucket I I I I I X Image: Ima</td><td>% remaining N W G O D U S B B B B B B B C R F P A A C N A Comments Parts % remaining N W V D I I V C N Comments Parts I I I I I V C I V C N Comments Parts I I I I I V C I I I I I I I I V C I I I I I I I I I I I I</td><td>% remaining N G Å P Å N Comments Parts Labour % remaining N N N L N N Comments Parts Labour Main N I I I I I N has a mulcher not a bucket Image: Note that the second seco</td></td<>	% remaining N G V R P A A A A A A A A C A A C A A C A A C A A C A A C A A C A A C A A C A C A C A C A C A C A C A C C A C C A C C A C C C A C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C C	% remaining N W W G O D A B E A A A E N A A A A A % remaining N W D I I I X I I I I I X I I I I I X I I I I I X I I I I I X I I I I I X	% remaining N W G O D A E A A A A N A Comments % remaining N W I I I I A Comments I I I I I I X has a mulcher not a bucket I I I I I X Image: Ima	% remaining N W G O D U S B B B B B B B C R F P A A C N A Comments Parts % remaining N W V D I I V C N Comments Parts I I I I I V C I V C N Comments Parts I I I I I V C I I I I I I I I V C I I I I I I I I I I I I	% remaining N G Å P Å N Comments Parts Labour % remaining N N N L N N Comments Parts Labour Main N I I I I I N has a mulcher not a bucket Image: Note that the second seco

UNDERCARRIAGE MEASUREMENTS

				Estimated Cost			
	Dimension	% remaining	Comments	Parts	Labour	Tota	
Track Links		30%	links are heavily worn and have a fair bit of play				
Track Bushings Chain sealed and lubricated? Ves No Have pins/bushings been turned? Ves No		30%	pins haven't been turned and aren't lubricated not good				
Track Pitch		20%	have been worn down pretty bad, cracked or broken				
Grousers - Shoes		20%	also been worn down bad				
ldlers		50%	in good shape, still role and are not blown up yet				
Carrier Rollers		50%	in good condition still rollin no flat spots or bearing fail				
Track Rollers		50%	good condition no bearing failiure or leaking				
Sprockets		50%	good condition, no excessive side wear and or broken ears				

ADDITIONAL PHOTOS





